

ECHNICAL Technical Q & A

Upward Deflection of Truss Bottom Chords

by Ryan J. Dexter, P.E.

The condition of truss arching is explored.

artition separation is defined by our industry as the cracking that develops at the interface between interior partition walls and ceiling or floor finishes, usually characterized by gaps that open in the winter and close in the summer. There are many reasons that cause partition separation, including what is termed "truss arching" by many in the field. From the calls we receive on this issue, truss movement is often blamed; but in actuality, truss movement causes partition separation in only a minority of the cases.

Let's take a look at why arching occurs and the degree to which it impacts truss deflection.

Truss arching is best described as an upward deflection of a truss resulting from a differential elongation or shrinkage between the top and bottom chords. Recall that wood swells as its moisture content increases and shrinks as its moisture content decreases. Therefore, an increase in the moisture content of the top chord relative to the bottom chord will cause an elongation of the top chord relative to the bottom chord. Similarly, a decrease in the moisture content of the bottom chord relative to the top chord will cause shrinkage in the bottom chord relative to the top chord. Since typically the top and bottom chords of a roof truss are firmly connected at the heel joint by a metal connector plate, if the differential movement between the chords is large enough, an "arching" or upward deflection (most pronounced at the midspan of the truss) can occur.

Truss arching has been known to occur during the winter following "close-in"; this is when the trusses were installed late in the year after having been subjected to wet or humid weather. The bottom chords of the trusses are typically enclosed in insulation and immediately begin "drying out" due to the heat from the living area below. In this scenario, the bottom chord begins to dry at a much faster rate than the top chord, causing shrinkage in the bottom chord relative to the top chord, which results in an upward movement of the trusses. If these trusses cross over interior partition walls that are nailed directly to the bottom chord of the truss, the arching of the bottom chord can cause a crack or gap to form at the corner joint between the ceiling and the top of the partition wall, or can actually lift the partition off of the floor below. In this situation, the arching will typically dissipate as the moisture content of the top and bottom chords equilibrate to the same level.

Truss arching has also been known to occur in existing structures on a seasonal basis, which usually indicates that the ventilation in the attic is inadequate, or that moisture from the house is escaping into the attic as opposed to being vented directly outdoors.

at a glance

- ☐ Partition separation is often blamed on a condition known as truss arching.
- ☐ Wood may expand or shrink depending on its moisture content.
- ☐ The example given in Figure 2 shows that a 28-ft truss with 19% moisture content that dries to 7% may cause an upward deflection of about 0.7 inches.
- Many factors lead to partition separation; the only way to prove truss arching is to use a laser level to assess all the areas of potential movement in the structure.

Example Calculation for Truss Arching

The following table shows the average longitudinal elongation/shrinkage values per 1% change in moisture content of three lumber species commonly used in metal plate connected wood truss construction:

Species	Changes Per 1% Loss in Moisture Content
Southern Pine	0.0127%
Douglas Fir-Larch	0.0073%
Hem-Fir	0.0063%

Continued on page 12

New WTCA Members

REGULAR MEMBERS

A-1 Roof Trusses

4451 Saint Lucie Blvd Fort Pierce, FL 34946-9035 772/409-1010 Mr. John Herring

A. Potvin Construction

PO Box 969 Rockland, ON K4K 1L6 613/446-2203 Mr. Guy Simard

Bellbird Building Supplies

235 Princes Hwy Melbourne, VIC 3803 AUSTRALIA +61 3 9703 2444 Mr. Michael Tremewen

Circle Three Industries

PO Box 3036 Post Falls, ID 83877 208/773-7755 Mr. Carl Broadbent

Maki Corp.

101 Linus Allain Ave Gardner, MA 01440 978/630-3916 Mr. Kevin LaClaire

Modu-Tech

1200 E Patapsco Ave Baltimore, MD 21225-2233 410/355-1014 Mr. Mike Pigozzi

Mountain Grove Components 211 S Oak St

Mountain Grove, MO 65711 417/926-1311 Ms. Melanie W. Thompson

Pecos Valley Homes

96 San Marcos Loop Santa Fe, NM 87508 505/424-1141 Mr. Carl Douglass Sponsor: Mr. James Swanson

Penn-Truss Manufacturing, Inc.

PO Box 418 Saltcoats, SK SOA 3R0 306/744-2403 Mr. Colin Penner

Pine Lodge Truss, Inc.

103 W Pine Lodge Rd Roswell, NM 88201-9435 505/623-9500 Mr. Gordon Wheat

Precision Framing System, Inc.

11922 General Dr Charlotte, NC 28273 704/588-6680 Mr. Philip Zurawski Sponsor: Mr. Glenn Traylor

Rosamond Truss Inc.

PO Box 1876 Rosamond, CA 93561-1876 661/256-8575 Mr. Jim Browne

The Truss Company

4520 N St Louis St Batesville, AR 72501-8233 870/793-5134 Mr Vance Jarrett

Timber-Tech Truss Inc.

Box 121 Aldersyde, AB TOL 0A0 403/601-4565 Ms. Wendy Going

Titan Truss LLC

1108 14th St #431 Cody, WY 82414-3743 307/587-2187 Mr. Denny McVey

WBC Building Components

PO Box 1447 Columbia Falls, MT 59912 406/892-2171 Mr. Donald McGrady Sponsor: Mr. Larry Pomeroy

ASSOCIATE MEMBERS

Mr. Kevin Beckstead 2730 N 4800 W

Corrine, UT 84307 435/744-5511

Bloch Lumber Company

123 N Wacker Dr Ste 1350 Chicago, IL 60606-1772 312/466-4500 Mr. Gregg S. Riley

Ferris Home Consulting

575 Bridge Rd Unit 10-5 Florence, MA 01062-1089 413/575-8802 Mr. Bradley Ferris

Fournier Industries

3787 West Frontenac Blvd Thetford Mines, QC G6H 2B5 418/423-4241 Mr. Gaston Tanguay

Lenard Gabert & Associates

3801 Kirby Ste 415 Houston, TX 72098 713/527-0251 Mr. Lenard M. Gabert

My Builder LLC

5756 Lake Court NW Kennesaw, GA 30152 770/595-5143 Mr. Angelo Sciortino

Packer Engineering

PO Box 353 Naperville, IL 60566-0353 630/577-1964 Mr. Mike Cahill

16085 Fish Rd Ste 10 Marysville, OH 43040-8925 614/214-1487 Mr. Michael R. Parks

Trehel CorporationPO Box 1707


Clemson, SC 29678 864/654-6582 Mr. David Stokes

Listing as of 10/15/08.

For more information about WTCA membership, contact Anna (608/310-6719 or astamm@qualtim.com) or visit www.sbcindustry.com.



For reader service, go to www.sbcmag.info/klaisler.htm



For reader service, go to www.sbcmag.info/finnforest.htm

November 2008 Structural Building Components Magazine www.sbcmag.info November 2008 Structural Building Components Magazine www.sbcmag.info

We Sleep Well at Night!

Why? Because we sell solutions, not machinery. Of course, the solutions ultimately result in machinery sales, but we are promoting the equipment that fits the solution, not the equipment that optimizes our commission. Add the fact that we promote truss, wall panel and door equipment manufacturers that take pride in quality and service, and it's easy to see why we don't toss and turn.



800/382-0329 phone • 402/438-2524 fax sales@wasserman-associates.com

Not Comfortable with Used Equipment?

Please consider the following:

- Satisfaction Guaranteed—if it's not right, we'll buy it back!
- Installation Services Available
- Leasing Available
- Shipping Coordination Is Included

Please contact us to sell your excess equipment!

For reader service, go to www.sbcmag.info/wasserman.htm


Technical Q&A

Continued from page 10

As an example of how truss arching can occur, let's assume we have a 28-ft span truss with an average moisture content of 19% that is installed in the roof of a house in northern Virginia in late November. Assume that Southern Pine is used in the chords and webs of this truss. Assume also that the house is quickly enclosed after the trusses are set with heat applied to the interior to aid with the finishing of the drywall and that the bottom chord is completely enclosed in insulation soon after (see Figure 1). Under these conditions the bottom chord dries over a couple of months from 19% to 7%. This equates to a 12% difference in moisture content. Meanwhile, the moisture content in the top chord remains relatively unchanged.

If southern pine shrinks 0.0127% per each 1% loss in moisture content, we can expect shrinkage of approximately 0.001524 in./in. due to the 12% loss (i.e., $0.000127 \times 12 = 0.001524 \text{ in./}$ in.). The bottom chord is 336 in. long (i.e., 12 in./ft. x 28 ft.). Therefore, the potential overall shrinkage of the bottom chord is approximately $0.001524 \times 336 \text{ in.} = 0.512 \text{ in.}$

Because the bottom chord is restrained by the top chord and the webs (also because the chords are typically constrained at the heels due to the bearing connection), this shortening could potentially produce an upward deflection of the bottom



chord of approximately 0.70 in. using the mathematical relationships between an arch and chord of a circle (see Figure 2).

The above example is idealized. Remember that the percentages listed in Figure 1 are averages. This means that because of variations between species, variations between trees from different forests, the age of the trees when cut, and variations in the lumber within the same tree, elongation and shrinkage does not always take place uniformly, and sometimes does not occur at all. In addition, slight slippage of the wood around the metal teeth of the truss plate, the orientation of the growth rings in the lumber, the number of pieces used to form the lower chord, the way the trusses are fastened to the walls, the amount of ventilation, the relative humidity, and the thickness of the insulation make predicting when partition separation will occur very difficult if not impossible.

Because of all these reasons and the fact that truss movement is not typically found to be the cause when a rigorous assessment of movement in the building is made, it is generally not reasonable to blame trusses for partition separation. The only way to know for sure that truss movement is taking place is to use a laser level to assess all the areas of potential movement in the structure. The foundation must be level, the walls square, the top plates level, the floor level and so forth Building shrinkage/movement can come from a variety of sources. Once the cause is known, remediation is easier.

Again, truss arching is just one of several factors that can cause partition separation. We have provided a way to quickly assess the amount of relative shrinkage that the lumber used in a truss may accrue. This is intended to provide information that will help the evaluation of truss movement in a building. To learn more about the factors that can cause partition separation refer to WTCA's Truss Technology on Building (TTB) brochure, Partition Separation Prevention and Solutions, available at <u>www.sbcindustry.com/ttbpartsep</u>. **SBC**

To pose a question for this column, call the WTCA technical department at 608/274-4849 or email technicalga@sbcmag.info.

READY TO JOIN THE SCORE RANKS?



www.trusssystemsinc.com

Oxford, GA





Cascade Mfg Co

www.cascade-mfg-co.com Cascade, IA

True House, Inc. www.truehouse.com Jacksonville, FL

Truss Craft www.dakotacraft.com

Chevenne, WY Truss Systems, Inc.

Tri-County Truss, Inc.

www.tricountytruss.com

Burlington, WA

Lumber Specialties www.lbrspec.com Dyersville, IA

Dakota Craft Truss www.dakotacraft.com Rapid City, SD

Plum Building Systems, LLC www.plumbuildingsystemsinc.com West Des Moines, IA

ProBuild Manufacturing www.carterlee.com

Indianapolis, IN

Shelter Systems Limited

www.sheltersystems.com Westminster, MD

Sun State Components of Nevada, Inc.

www.sunstatenv.com North Las Vegas, NV

Buy a package subscription and be well on your way!

SCORE package subscriptions are available for each level of certification.



- These packages bundle required programs together and offer them all to you at an average of 50% OFF STANDARD PRICES! *
 - This is your way to get SCORE certified quickly, economically and at whatever level you choose. *
- Find out more, and how to get your dues reduced, at www.sbcindustry.com/scorepackages.php.



Structural Building Components Magazine November 2008 www.sbcmag.info



www.sbcmag.info

Dear Reader:

Copyright © 2008 by Truss Publications, Inc. All rights reserved. For permission to reprint materials-from *SBC Magazine*, call 608/310-6706 or email editor@sbcmag.info.

The mission of *Structural Building Components Magazine (SBC)* is to increase the knowledge of and to promote the common interests of those engaged in manufacturing and distributing of structural building components to ensure growth and continuity, and to be the information conduit by staying abreast of leading-edge issues. SBC will take a leadership role on behalf of the component industry in disseminating technical and marketplace information, and will maintain advisory committees consisting of the most knowledgeable professionals in the industry. The opinions expressed in SBC are those of the authors and those quoted solely, and are not necessarily the opinions of any affiliated association (WTCA).

